

## WEST Search History

DATE: Sunday, December 24, 2006

Hide?	<u>Set</u> <u>Name</u>	<u>Query</u>	<u>Hit</u> <u>Count</u>
	<i>DB=PGPB,USPT; PLUR=YES; OP=OR</i>		
<input type="checkbox"/>	L17	L16 and @pd > 20060623	5
<input type="checkbox"/>	L16	L12 or L11	75
<input type="checkbox"/>	L15	L13 and L9	0
<input type="checkbox"/>	L14	(steel and (normalize or normalized or normalizing) and creep and ("coarse carbide" or "creep damage" or haz or "heat affected zone")).clm.	0
<input type="checkbox"/>	L13	L12 not L11	53
<input type="checkbox"/>	L12	(steel and (normalize or normalized or normalizing) and creep and ("coarse carbide" or "creep damage" or haz or "heat affected zone"))	57
<input type="checkbox"/>	L11	(steel and (normalize or normalized or normalizing) and creep and ("type 4" or "type IV"))	22
<input type="checkbox"/>	L10	(steel and (normalize or normalized or normalizing) and creep and ("type 4" or "type IV")).clm.	0
<input type="checkbox"/>	L9	(428/681 or 428/682 or 428/683 or 148/516 or 148/519 or 148/521 or 148/529 or 228/262.41)! [CCLS]	1736
	<i>DB=EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>		
<input type="checkbox"/>	L8	("type 4" or "type IV") and creep and steel and (normalize or normalized or normalizing)	0
<input type="checkbox"/>	L7	L6 or L4	35
<input type="checkbox"/>	L6	L5 not L4	28
<input type="checkbox"/>	L5	steel and (normalize or normalizing) and (haz or "heat affected zone")	29
<input type="checkbox"/>	L4	L2 or L1	7
<input type="checkbox"/>	L3	L2 not L1	5
<input type="checkbox"/>	L2	steel and (haz or "heat affected zone") and ("coarse carbide" or "creep damage")	6
<input type="checkbox"/>	L1	steel and (normalize or normalizing) and ("coarse carbide" or "creep damage")	2

END OF SEARCH HISTORY